

CODES AND TECHNICAL STANDARDS COMMITTEE
FORMAL INTERPRETATION

REFERENCE NUMBER: 82.224.161.97.08

REFERENCE DOCUMENT: Life Safety Code 1994 Existing 13-3.2.1, 13-3.2.2, and A-13-3.2.2

LOCATION: PHOENIX AREA INDIAN HEALTH SERVICE
PHOENIX, AZ

QUESTION: Phoenix Area Division of Facility Management requests authority to build laboratories which do not meet NFPA-99, Chapter 10 and NFPA-45.

ANSWERS: Authority not recommended

COMMENTS: Each Laboratory setup and requirements could be unique using various quantities and types of chemicals. The code shall be interpreted individually by the authority having jurisdiction.

Signatures:

<input checked="" type="checkbox"/> Agree		
<input type="checkbox"/> Disagree	/Steven L Bourn/ Steven L Bourn, R.A. (ES-Dallas)	DATE: 5-7-97
<input checked="" type="checkbox"/> Agree		
<input type="checkbox"/> Disagree	/Mark P Burke/ Mark Burke, E.I.T. (ES-Dallas)	DATE: 5-7-97
<input checked="" type="checkbox"/> Agree		
<input type="checkbox"/> Disagree	/Gerry M. Shaffer/ Gerry Shaffer, R.A. (ES-Dallas)	DATE: 5-12-97
<input checked="" type="checkbox"/> Agree		
<input type="checkbox"/> Disagree	/Yusuf Vora/ Yusuf Vora, P.E.(ES-Dallas)	DATE: 5-7-97
<input checked="" type="checkbox"/> Agree		
<input type="checkbox"/> Disagree	/Howard R. Minter/ Howard Minter, P.E.(ES-Dallas)	DATE: 5-7-97
<input checked="" type="checkbox"/> Agree		
<input type="checkbox"/> Disagree	/Diane Stewart Adams/ Diane Stewart Adams, P.E. (ES-Seattle)	DATE: 6-12-97